

Overall Description

There is no elevator located within the building. The Basement of Harder House has an ADA entrance located on the very southeast corner of the building that can be accessed from the nearby parking lot located directly south of the building. Space is mostly made up of suites and some mechanical space.

Restrooms

Room 5 is a single-occupancy, all-gender restroom.

Wheelchair Accessible Entrances and Exits

Wheelchair entry into the building can only be made via the basement level. Wheelchairs enter the parking lot located on SW Mill St and S 10th Ave using the ramp leading to the building.

Elevators

There is no elevator located in the Harder House building.

Stairs

Stairwell S1 is located along corridor C1. This stairwell has access to the Basement through Floor 2.

Overall Description

On Floor 1 of Harder House, the main space is made up of multiple office spaces. The entrance is on the west side of the building and is not ADA accessible. There is also an entrance on the northeast side of the building and is also not ADA accessible.

Restrooms

There is no restroom located on Floor 1. A restroom can be found on the basement floor or Floor 2.

Wheelchair Accessible Entrances and Exits

Wheelchair entry into the building can only be made via the Basement using the ramp located on the southeast side of the building. Wheelchairs enter the parking lot on SW Mill St and S10th Ave. Wheelchair access to Floor 1 cannot be made.

Elevators

There is no elevator located in the Harder House building.

Stairs

Stairwell S101 is located just north of corridor C101 with an entry to the stairwell on both the west and east side. This stairwell has access to the Basement through Floor 2.

Overall Description

On Floor 2 of Harder House, space is mainly office suites. There are about 5 rooms on this floor. There is also another restroom located towards the east side of the building.

Restrooms

Room 205 is a single-occupancy, all-gender restroom located at the very east end of corridor C201.

Wheelchair Accessible Entrances and Exits

Wheelchair access to Floor 2 cannot be made.

Elevators

There is no elevator located in the Harder House building.

Stairs

Stairwell S101 is located just north of vestibule v201 and south of suite 201. This stairwell has access to the Basement through Floor 2.

Overall Description

The roof of HAR is a restricted area and is not accessible to the public.