

Overall Description

On the first floor of the Art Building, two elevators, E184 and E185, are located on the southeast side of the building. Stairwell S101 is located east of the elevators, with a custodial room to the west. Event Commons 129 is located north of the elevators, and Corridor C100 is located south of the elevators. Corridor C100 is bordered by Suite 100 to the south, Room 114 to the west, and Room 112 to the north. The corridor connects to Corridors C101 and C103 to the north. Corridor C101 connects to Corridor C102 to the north and provides access to Event Commons 131 and the 131 restroom to the east. Corridor C103 is bordered by Rooms 160–170 to the east and Room 156 and the 131 restroom to the west. Corridor C102 is bordered by Rooms 150–156 to the north and Bike Storage 141, Stairwell S102, and the 131 restroom to the south.

Restrooms

A multi-stall all-user restroom is located southeast of corridor C102.

Wheelchair Accessible Entrances and Exits

Wheelchair access to the first floor is located on the west and east side of the building and by a ramp located on the north side of the building that leads to entrances on the south side of the building.

Elevators

There are two elevators located on the southeast side of the building. Elevators E184 and E185 provide access to all floors of the building.

Stairs

Stairwell S101 is located north of corridor C100. Stairwell S102 is located southwest of corridor C102. Stairwell S103 is located southwest of corridor C104. The S101 and S102 stairwells have access to all floors.

Overall Description

On the second floor of the Art Building, two elevators, E284 and E285, are located on the southeast side of the building. Stairwell S201 is located east of the elevators, with room 205 to the west. Room 229 is located north of the elevators, and Corridor C200 is located south of the elevators. Corridor C200 is bordered by room 200-206 to the south, corridor C201 to the west, and Room 205 to the north. The corridor connects to Corridor C203 to the north. Corridor C101 connects to Corridor C102 to the north, Rooms 220-224 and Corridor C204 to the West, and provides access to the 231 restroom to the east. Corridor C204 connects to Room 208 and 214 to the north and Room 207-219 to the south. Corridor C203 is bordered by Rooms 260-264 to the east and Room 256 and the 231 restroom to the west. Corridor C202 is bordered by Rooms 250-256 to the north and Rooms 247-251, Stairwell S202, and the 231 restroom to the south.

Restrooms

A multi-stall all-user restroom is located southeast of corridor C202.

Wheelchair Accessible Entrances and Exits

Wheelchair access to the second floor is made by elevator and can be accessed from the first floor.

Elevators

There are two elevators located on the southeast side of the building. Elevators E284 and E285 provide access to all floors of the building.

Stairs

Stairwell S201 is located north of corridor C200. Stairwell S202 is located southwest of corridor C202. Stairwell S203 is located southwest of corridor C204. The S201 and S202 stairwells have access to all floors.

Overall Description

On the third floor of the Art Building, two elevators, E384 and E385, are located on the southeast side of the building. Stairwell S301 is located east of the elevators, with room 305 to the west. Room 329 is located north of the elevators, and Corridor C300 is located south of the elevators. Corridor C300 is bordered by Room 300 and Corridor C305 to the south and Room 305 to the north. The corridor connects to Corridor C303 and C301 to the north. Corridor C305 is bordered to the west by Rooms 307-313. Corridor C301 connects to Corridor C302 to the north, and provides access to the 331 restroom to the east. Corridor C303 is bordered by Rooms 360-364 to the east and Room 361 and the 331 restroom to the west. Corridor C302 is bordered by Rooms 350-352 to the north and Rooms 347-351, Stairwell S302, and the 331 restroom to the south.

Restrooms

A multi-stall all-user restroom is located southeast of corridor C302.

Wheelchair Accessible Entrances and Exits

Wheelchair access to the third floor is made by elevator and can be accessed from the first floor.

Elevators

There are two elevators located on the southeast side of the building. Elevators E384 and E385 provide access to all floors of the building.

Stairs

Stairwell S301 is located north of corridor C300. Stairwell S302 is located southwest of corridor C302. The S301 and S302 stairwells have access to all floors.

Overall Description

On the fourth floor of the Art Building, two elevators, E484 and E485, are located on the southeast side of the building. Stairwell S401 is located east of the elevators, with room 405 to the west. Room 429 is located north of the elevators, and Corridor C400 is located south of the elevators. Corridor C400 is bordered by Room 400-413 and Corridor C405 to the south, and Room 405 to the north. The corridor connects to Corridor C403 and C401 to the north. Corridor C401 connects to Corridor C402 to the north, and provides access to the 431 restroom to the east. Corridor C403 is bordered by Rooms 460-464 to the east and Room 461 and the 431 restroom to the west. Corridor C402 is bordered by Rooms 450-458 to the north and Rooms 447-451, Stairwell S402, and the 431 restroom to the south.

Restrooms

A multi-stall all-user restroom is located southeast of corridor C402.

Wheelchair Accessible Entrances and Exits

Wheelchair access to the fourth floor is made by elevator and can be accessed from the first floor.

Elevators

There are two elevators located on the southeast side of the building. Elevators E484 and E485 provide access to all floors of the building.

Stairs

Stairwell S401 is located north of corridor C400. Stairwell S402 is located southwest of corridor C402. The S401 and S402 stairwells have access to all floors.

Overall Description

The Art Building roof is restricted access and cannot be accessed by a public entrance.